



Figure 1: Pinout diagrams for the male ELCO connector (left) and the male 8-pin miniature CPC connector (right). The CPC connector is only for motors up to 1.0 Amps.

Table 1: MHATT-CAT configuration of motors

Connector		Signal	SLO-SYN	SLO-SYN	SLO-SYN 8-wire	Vexta
ELCO	CPC	(phase)	4-wire motor	6-wire motor	motor (serial mode)	motor
A	1	1 out	red	red	red	black
В	3	1 return	red/white	red/white	red/white	green
С	2	2 out	white/black	green	green	red
D	5	2 return	black	green/white	green/white	blue
E *				black	black and white †	yellow
J *				white	orange and white/black †	white

^{*} not required for MHATT-CAT, but suggested; alternatively, isolate these leads

Table 2: MHATT-CAT configuration for limit switches

Conne	ector	Limit switch	
ELCO	CPC	connection	
W	6	High limit	
Т	4	*High limit return	
X	8	Low limit	
U	7	*Low limit return	

^{*} both limit returns are connected

[†] must connect these wires together